


Facility Service Company, Inc.
14607 Rothgeb Drive
Rockville, MD 20850
Tel: 301-340-2665

QUOTE

Date	Quote #
9/11/2020	Q200911.015

Tanyard Spring HOA
 c/o Abaris Realty, Inc.
 7811 Montrose Road, #110
 Potomac, MD 20854

Description	Rate	Total
<p>Kinglets Roost Lane - (Erosion Work):</p> <p>Excavate as needed to create free flowing grade towards storm water basin. Install 5-8" size rip rap. Rip rap that adjoins path will be mortared in order to prevent under washing the edge of asphalt path 40' x 6. Total cost for items/services listed above:</p> 	3,200.00	3,200.00

Subtotal	\$3,200.00
Sales Tax (0.0%)	\$0.00
Total	\$3,200.00

Facility Service Co., Inc. is not responsible for damage to any unmarked private utilities.
 NOTE: This quotation is valid for thirty days from date of issue and subject to availability

Proposed by:

 Facility Service Co., Inc.

Accepted by:

Shuren Anderson 10-15-20

 Contracting Officer Date