



29 Apples Church Road
 Thurmont, MD 21788
 (800) 385-0075
 www.playspec.com

ADDRESS
 TANYARD SPRINGS HOA
 ATTN MARK MOORMAN
 6920 HERITAGE CROSSING
 GLEN BURNIE, MD 21060

SHIP TO
 TANYARD SPRINGS HOA
 OPTION #2
 C/O PLAYGROUND
 SPECIALISTS

Proposal 22840A

DATE 10/01/2020

SALES REP
 DAVE SMITH

TYPE	QTY	RATE	AMOUNT
REMOVAL REMOVE AND DISPOSE OF EXISTING DAMAGED GEO DIAGONAL CLIMBER AND FOUR (4) BELLS - INCLUDES DUMPSTER CHARGES	1	850.00	850.00
PARTS ZZEX4570 - PLAYSET	1	725.00	725.00
PARTS AAU0092 - 10" BELL	1	101.00	101.00
PARTS AAU0094 - 8" BELL	1	75.00	75.00
PARTS AAU0095 - 7" BELL	2	65.50	131.00
PARTS ZZCH4095 - CENTERLINE PIPE WALL BARRIER	1	525.00	525.00
PARTS ZZUN4299 - STEERING WHEEL	1	175.00	175.00
INSTALLATION CERTIFIED INSTALLATION OF ALL PARTS ABOVE	1	840.00	840.00

*50% deposit. Balance due net 30 unless otherwise noted.
 *3% service charge for all credit card payments.
 *Pricing only guaranteed for 30 days unless specified above.
 *Absolutely no engineering, permit fees, bonding, or additional
 insurance included in above pricing unless specified on line item.
 *Additional mobilization, poor soils, limited access, or utility
 issues may result in change orders.
 *Standard lead times always apply. Contact sales agent for
 details.
 **Sign and return when approved. Thank you!

SUBTOTAL	3,422.00
TAX (0.06)	103.92
SHIPPING	179.00

TOTAL \$3,704.92