

Facility Service Company, Inc.  
 14607 Rothgeb Drive  
 Rockville, MD 20850  
 Tel: 301-340-2665

# QUOTE

Date	Quote #
6/4/2020	Q200604.002

Tanyard Spring HOA  
 c/o Abaris Realty, Inc.  
 7811 Montrose Road, #110  
 Potomac, MD 20854

Description	Rate	Total
<p>French Drain - (1101 - 1139 Colbourn Corner):</p> <p>French drain will be installed behind the residences 1101 - 1139 Colbourn Corner.            Drain will measure 526' long with a surface swale of 3' wide.            Soil will be excavated to a depth of 2'.            Drain will be lined with 4 oz. non-woven filter cloth.            Drain will be filled with #57 gravel.            6" PVC perforated pipe will be located in the drain.            Drain will run the entire length from 1101 down to 1139 before being discharged into the storm drain that sits behind 1139.            3-4" of topsoil will be placed on top of filter cloth wrapped gravel.            Install seed &amp; erosion control netting.            Turf damaged during drain installation will be repaired by adding topsoil &amp; seeding.            All debris associated with this work will be disposed of off-site.            Total cost for services/items listed above:</p>	18,936.00	18,936.00

Facility Service Co., Inc. is not responsible for damage to any unmarked private utilities.  
 NOTE: This quotation is valid for thirty days from date of issue and subject to availability

<b>Subtotal</b>	\$18,936.00
<b>Sales Tax (0.0%)</b>	\$0.00
<b>Total</b>	\$18,936.00

Proposed by:

Accepted by:

\_\_\_\_\_  
 Facility Service Co., Inc.

*Shirley Anderson* 7-15-20  
 \_\_\_\_\_  
 Contracting Officer Date