



# Proposal

Where Amazing Happens...

**Client Name:** Tanyard Springs HOA  
**Project Name:** BUDGET 2019 - Replace Sand, Gravel and Laterals in TR60 Wading Pool Filter  
**Jobsite Address:** 6920 Heritage Crossing Glen Burnie, MD 21060 **Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST1041723  
**Date:** Aug 23, 2018

**Wading Pool - Replace Sand, Gravel and Laterals in TR60 Filter** **\$510.00**

Job Description:

- Remove and dispose all sand and gravel from filter tank
- Remove and dispose all laterals
- Flush filter with water
- Install new laterals
- Put new sand and gravel into filter tank

<b>Subtotal</b>	<b>\$510.00</b>
<b>Taxes</b>	<b>\$0.00</b>
<b>Estimate Total</b>	<b>\$510.00</b>

All Unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above work.

Estimate authorized by: \_\_\_\_\_  
 Signature Date: \_\_\_\_\_

Estimate approved by: *[Signature]*  
 Customer Representative  
 Signature Date: 8-25-19

2704 Columbia pike  
 Arlington, VA 22204  
 BUDGET 2019 - Replace Sand, Gravel and Laterals in TR60 Wading Pool Filter [EST1041723]

P. (703) 920-1750  
 F. (703) 920-1753  
 www.highsierrapools.com  
 email: service@highsierrapools.com  
 Page 1 of 1



# Proposal

### Where Amazing Happens...!

**Client Name:** Toneyard Springs HOA  
**Project Name:** BUDGET 2019 - Replace Main Drain Covers in Main Pool to Comply with VGB Safety Act  
**Job/fe Address:** 6920 Heritage Crossing Glen Burnie, MD 21060 **Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST1043440  
**Date:** Aug 24, 2018

## Main Pool - Replace Main Drain Covers (VGB Safety Act) \$1,035.00

Existing Lawson main drain covers have life span of 10 years. High Sierra Pools strongly recommends replacement of those covers as soon as possible.

POOL MUST BE DRAINED.

FOR UNDERWATER INSTALLATION ADDITIONAL CHARGES WILL BE APPLIED.

IT IS EXPECTED THAT COVER FRAME AND SCREW HOLES ARE IN GOOD CONDITION AND COMPATIBLE WITH NEW MAIN DRAIN COVER. IF ANY PROBLEMS ARE DISCOVERED DURING INSTALLATION OF NEW MAIN DRAIN COVER, MANAGEMENT WILL BE INFORMED AND ADDITIONAL PROPOSAL WILL BE SUBMITTED.

<b>Subtotal</b>	<b>\$1,035.00</b>
<b>Taxes</b>	<b>\$0.00</b>
<b>Estimate Total</b>	<b>\$1,035.00</b>

All Unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above work.

Estimate authorized by: \_\_\_\_\_

Estimate approved by: \_\_\_\_\_

Company Representative

Customer Representative

Signature Date: \_\_\_\_\_

Signature Date: \_\_\_\_\_

*Jayla Walters*  
 Customer Representative  
 8-25-19

2704 Columbia pike  
Arlington, VA 22204

P. (703) 920-1750  
F. (703) 920-1753

www.highsierrapools.com  
email: service@highsierrapools.com

BUDGET 2019 - Replace Main Drain Covers in Main Pool to Comply with VGB Safety Act [EST1043440]



# Proposal

**Where Amazing Happens...!**

**Client Name:** Tanyard Springs HOA  
**Project Name:** 2019 Pool Supplies  
**Jobsite Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST1293887  
**Date:** Apr 23, 2019

**2019 Pool Supplies**

**\$1,089.12**

1	Each	Plastic Sloping Ladder Tread Step for Guard Stand		\$125.00
1	Each	Purex #072795 S.S.Basket For	Purex #072795 S.S.Basket For C" Pumps C-29 11"-Old S01200	\$463.12
3	Each	Skimmer Weir - 7-5/8	Skimmer Weir - 7-5/8 Sylvan/Hayw Subst L1932	\$78.00
2	Each	Mec-O-Matic #8800637 Tube Repl	Mec-O-Matic #8800637 Tube Repl Kit (Peristaltic) 7/16	\$80.00
2	Each	Mec-O-Matic U8800712 1/4 Inj.	Mec-O-Matic U8800712 1/4 Injection Fitting	\$100.00
1	Each	Leaf Rake - H.D.Aluminum	Leaf Rake - H.D.Aluminum W/ Snap Handle #21196	\$62.00
1	Each	First Aid Kit-Commercial #50	Order In Lots Of 48 24200 Replaces 6450	\$95.00
1	Each	Taylor Test Kit K-2005C-8 - INCLUDED IN CONTRACT	Taylor Test Kit K-2005C-8 Liquid Dpd - Service Kit	\$0.00
1	Each	Brush-18" Algae S/S Alum. Backed	Brush-18" Algae S/S Alum. Backed Brush #718 12 Pk 18" Algae Ss Bristle	\$50.00
2	Each	Ladder Bumper (Sold as Each)	Ladder-Male Bumpers Sold As Each	\$36.00

**Subtotal** \$1,089.12  
**Taxes** \$0.00

**Estimate Total \$1,089.12**

TERMS AND CONDITIONS: All Unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above

work. Price is valid for 90 days.

Estimate authorized by: \_\_\_\_\_  
Company Representative

Signature Date: \_\_\_\_\_

Estimate approved by:

*Jeffrey Walters*  
Customer Representative  
4-25-19

Signature Date:

2704 Columbia pike  
Arlington, VA 22204

p. (703) 920-1750  
f. (703) 920-1753



# Proposal

## Where Amazing Happens...

**Client Name:** Tanyard Springs HOA  
**Project Name:** Leak Repairs for Main Pool - Leak Survey Follow up  
**Jobsite Address:** 6920 Heritage Crossing Glen Burnie, MD 21060 **Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST1290364  
**Date:** Apr 22, 2019

### Replace Two Cracked Skimmers with Equalizer Line

**\$3,300.00**

- Break existing skimmer pad or saw cut and remove 2 ft. by 2 ft. section of deck around skimmer
- Perform initial pressure test to ensure skimmer line is intact.
- Excavate around skimmer and remove and dispose old skimmer.
- Reconnect new skimmer to existing pipe and install new skimmer at level with existing skimmer throat.
- Perform secondary pressure test of skimmer line.
- Extend skimmer crown to match level of the deck.
- Infill excavation with gravel and compact up to 4" below deck level)
- Pour concrete above the skimmer to form new skimmer pad (Approx. 4" thick), pad will be concrete with light broom finish
- Install grout to waterproof around skimmer throat.

#### Exclusions

- Structural repairs to the pool beam and skimmer mouth
- Repairs of broken underground pipe if initial pressure test fails.
- Installation of additional reinforcement (Concrete/Rebar) around skimmer body.
- Tile and coping work to skimmer throat.
- Damages to pool fixtures as resulting of proposed work
- Other unforeseen repairs required

### RegROUT Twelve Skimmer Throats

**\$900.00**

### Replace Three Hydrostatic Relief Valves

**\$375.00**

### Seal Seven Light Conduits

**\$525.00**

<b>Subtotal</b>	<b>\$5,100.00</b>
<b>Taxes</b>	<b>\$0.00</b>
<b>Estimate Total</b>	<b>\$5,100.00</b>

2704 Columbia Pike  
Arlington, VA 22204

Leak Repairs for Main Pool - Leak Survey Follow up [EST1290364]

www.highsierrapools.com  
email: service@highsierrapools.com

Page 1 of 2

10201019

**TERMS AND CONDITIONS:** All Unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above work. Price is valid for 90 days.

Estimate authorized by: \_\_\_\_\_

Company Representative

Signature Date: \_\_\_\_\_

Estimate approved by: \_\_\_\_\_

Customer Representative

Signature Date: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*[Faint, mostly illegible text from the reverse side of the page, including a list of items and a signature area.]*

00101019	10/10/19	10/10/19
00101019	10/10/19	10/10/19
00101019	10/10/19	10/10/19

2704 Columbia Pike  
Arlington, VA 22204

Leak Repairs for Main Pool - Leak Survey Follow up [EST1290364]

www.highsierrapools.com  
email: service@highsierrapools.com



# Proposal

Where Amazing Happens...!

**Client Name:** Tanyard Springs HOA  
**Project Name:** BUDGET 2019 - Replace Upper Bulkhead Fitting for One Filter and Sand, Gravel and Laterals in Four TR140 Main Pool Filters  
**Jobsite Address:** 6920 Heritage Crossing Glen Burnie, MD 21060 **Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST1041732  
**Date:** Aug 23, 2018

**Main Pool - Replace One Upper Bulkhead and Sand, Gravel and Laterals in FOUR TR140 Filters** **\$3,873.00**

- Remove and dispose all sand and gravel from all filter tanks
- Remove and dispose all laterals
- Remove one upper bulkhead fitting for one of the filters
- Flush filters with water
- Install new laterals
- Install new upper bulkhead fitting for one of the filters
- Put new sand and gravel into filter tanks

	<b>Subtotal</b>	<b>\$3,873.00</b>
	<b>Taxes</b>	<b>\$0.00</b>
	<b>Estimate Total</b>	<b>\$3,873.00</b>

All Unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above work.

Estimate authorized by: \_\_\_\_\_ Estimate approved by: *Jaylene Walters*  
 Company Representative Customer Representative  
 Signature Date: \_\_\_\_\_ 4-25-19



# Proposal

Where Amazing Happens...

**Client Name:** Tanyard Springs HOA  
**Project Name:** BUDGET 2019 - Replace Main Drain Covers in Wading Pool to Comply with VGB Safety Act  
**Jobsite Address:** 6920 Heritage Crossing Glen Burnie, MD 21060 **Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST1043453  
**Date:** Aug 24, 2018

## Wading Pool - Replace Main Drain Covers (VGB Safety Act)

\$290.00

Existing Hayward main drain covers have life span of 5 years. High Sierra Pools strongly recommends replacement of those covers as soon as possible.

POOL MUST BE DRAINED.

FOR UNDERWATER INSTALLATION ADDITIONAL CHARGES WILL BE APPLIED.

IT IS EXPECTED THAT COVER FRAME AND SCREW HOLES ARE IN GOOD CONDITION AND COMPATIBLE WITH NEW MAIN DRAIN COVER. IF ANY PROBLEMS ARE DISCOVERED DURING INSTALLATION OF NEW MAIN DRAIN COVER, MANAGEMENT WILL BE INFORMED AND ADDITIONAL PROPOSAL WILL BE SUBMITTED.

<b>Subtotal</b>	<b>\$290.00</b>
<b>Taxes</b>	<b>\$0.00</b>
<b>Estimate Total</b>	<b>\$290.00</b>

All Unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above work.

Estimate authorized by: \_\_\_\_\_

Company Representative

Signature Date: \_\_\_\_\_

Estimate approved by: \_\_\_\_\_

Customer Representative

Signature Date: \_\_\_\_\_


*John Walters*  
 4-25-19

2704 Columbia pike  
Arlington, VA 22204

p. (703) 920-1750  
f. (703) 920-1753

www.highsierrapools.com  
email: service@highsierrapools.com

BUDGET 2019 - Replace Main Drain Covers in Wading Pool to Comply with VGB Safety Act [EST1043453]



# Proposal

### Where Amazing Happens...

**Client Name:** Tanyard Springs HOA  
**Project Name:** 2019 Small pool repairs  
**Jobsite Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Billing Address:** 6920 Heritage Crossing Glen Burnie, MD 21060  
**Estimate ID:** EST11293875  
**Date:** Apr 23, 2019

### 2019 Small pool repairs

**\$650.00**

26	Each	Replace 6'x 6" Waterline Tile	\$650.00
<b>Subtotal</b>			\$650.00
<b>Taxes</b>			\$0.00
<b>Estimate Total</b>			<b>\$650.00</b>

**TERMS AND CONDITIONS:** All unforeseen conditions and work complications will be reported to the management. All Change orders are subject to prior approval. All work to be done in a professional manner and all materials to complete the above work to be included in this agreement. This estimate applies only to the job described above. The invoice will be submitted upon completion of the work. The payment is due upon receipt unless specified otherwise. Please sign below and return to the Sierra offices in order to schedule the above work. Price is valid for 90 days.

Estimate authorized by: \_\_\_\_\_

Company Representative

Signature Date: \_\_\_\_\_

Estimate approved by: \_\_\_\_\_

Customer Representative

Signature Date: \_\_\_\_\_

*Milan*  
 \_\_\_\_\_  
 Customer Representative  
 4-25-19

2704 Columbia pike  
 Arlington, VA 22204

p. (703) 920-1750  
 f. (703) 920-1753

www.highsierrapools.com  
 email: milan@highsierrapools.com